

Appendix G
Visual Analysis Table

| Visual Resource Survey: | | ERSP | Existing Conditions |
|-------------------------------------|---|---|---------------------|
| Key View: | | Eastside Road | |
| Date: | | 2/8/08 | |
| Viewpoint Description: | | View of pump station from Eastside Road. | |
| Photo Orientation: | | Northeast | |
| Viewer Position: | | _____ Inferior x Level _____ Superior | |
| View | Notes | | |
| Foreground (0 - 1/2 mile) | Foreground contains a curved roadway and dense vegetation including trees and underbrush. | | |
| Middleground (1/2 - 4 miles) | Not visible. | | |
| Background (> 4 miles) | Not visible. | | |
| Vividness | | | |
| Feature | Score* | Notes | |
| Landform | 4 | Not visible. | |
| Vegetation | 6 | Intact California oak woodland. | |
| Water Feature | n/a | | |
| Human-Made | 4 | The only human made element is the curved roadway. | |
| Overall | 4.7 | | |
| Intactness | | | |
| Overall | 6 | The scene is of an oak woodland slightly encroached upon by the roadway. | |
| Unity | | | |
| Overall | 6 | The image is a highly coherent view is of intact California oak woodland. | |
| Overall Visual Quality Score | 5.6 | | |

*Score Key:
1 - Very Low; 2 - Low; 3 - Moderately Low; 4 - Average; 5 - Moderately High; 6 - High; 7 - Very High

| Visual Resource Survey: | | ERSP | Without Landscaping |
|-------------------------------------|---|--|---------------------|
| Key View: | | Eastside Road | |
| Date: | | 2/8/08 | |
| Viewpoint Description: | | View of pump station from Eastside Road. | |
| Photo Orientation: | | Northeast | |
| Viewer Position: | | _____ Inferior x Level _____ Superior | |
| View | Notes | | |
| Foreground (0 - 1/2 mile) | In foreground, a brown building surrounded by a fence is visible. Vegetation has been cleared along the roadside and up the hill to accommodate the building. | | |
| Middleground (1/2 - 4 miles) | Not visible. | | |
| Background (> 4 miles) | Not visible. | | |
| Vividness | | | |
| Feature | Score* | Notes | |
| Landform | 5 | Hill behind pump station is now visible. | |
| Vegetation | 4 | Much of the oak woodland in image has been removed. | |
| Water Feature | n/a | | |
| Human-Made | 4 | The built elements now include the roadway and the pump station facilities. | |
| Overall | 4.3 | | |
| Intactness | | | |
| Overall | 3 | Pump station facility and obvious vegetation clearing encroach on what once a primarily natural setting. | |
| Unity | | | |
| Overall | 4 | Coherence of rural view diminished by addition of pump station and removal of all tree cover. | |
| Overall Visual Quality Score | 3.8 | | |

*Score Key:
1 - Very Low; 2 - Low; 3 - Moderately Low; 4 - Average; 5 - Moderately High; 6 - High; 7 - Very High

| Visual Resource Survey: | | ERSP | With Landscaping |
|-------------------------------------|---|---|------------------|
| Key View: | | Eastside Road | |
| Date: | | 2/8/08 | |
| Viewpoint Description: | | View of pump station from Eastside Road. | |
| Photo Orientation: | | Northeast | |
| Viewer Position: | | _____ Inferior x Level _____ Superior | |
| View | Notes | | |
| Foreground (0 - 1/2 mile) | Cleared hillside obscured by new plantings. | | |
| Middleground (1/2 - 4 miles) | Not visible. | | |
| Background (> 4 miles) | Not visible. | | |
| Vividness | | | |
| Feature | Score* | Notes | |
| Landform | 5 | Nominal change. | |
| Vegetation | 5 | Native species have been replanted. | |
| Water Feature | n/a | | |
| Human-Made | 4 | Nominal change. | |
| Overall | 4.7 | | |
| Intactness | | | |
| Overall | 5 | Replanting of native trees reduces the encroachment of the pump station. | |
| Unity | | | |
| Overall | 5 | Image composition is now relatively harmonious. Continuous corridor of vegetation up the hill enhances image. | |
| Overall Visual Quality Score | 4.9 | | |

*Score Key:
1 - Very Low; 2 - Low; 3 - Moderately Low; 4 - Average; 5 - Moderately High; 6 - High; 7 - Very High

| Visual Resource Survey: | | ERSP | Existing Conditions |
|--|---|--|---------------------|
| Key View: Private Property | | | |
| Date: 2/8/08 | | | |
| Viewpoint Description: View toward project from McDonough property front yard. | | | |
| Photo Orientation: Northeast | | | |
| Viewer Position: _____ Inferior _____ x _____ Level _____ Superior | | | |
| View | Notes | | |
| Foreground (0 - 1/2 mile) | Hills and valley visible in foreground. | | |
| Middleground (1/2 - 4 miles) | A line of hills visible in distance including a peak on the left side of the image. | | |
| Background (> 4 miles) | Not visible. | | |
| Vividness | | | |
| Feature | Score* | Notes | |
| Landform | 6 | Series of hills in foreground and middleground form an interesting composition. | |
| Vegetation | 6 | View of intact California oak woodland. | |
| Water Feature | n/a | | |
| Human-Made | 4 | Fences visible in the foreground. | |
| Overall | 5.3 | | |
| Intactness | | | |
| Overall | 6.5 | Except for the wire fences in the foreground, the image is free from encroachment. | |
| Unity | | | |
| Overall | 7 | Beautiful view of rolling hills of California oak woodland. | |
| Overall Visual Quality Score | 6.3 | | |

*Score Key:
1 - Very Low; 2 - Low; 3 - Moderately Low; 4 - Average; 5 - Moderately High; 6 - High; 7 - Very High

| Visual Resource Survey: | | ERSP | Without Landscaping |
|--|--|---|---------------------|
| Key View: Private Property | | | |
| Date: 2/8/08 | | | |
| Viewpoint Description: View toward project from McDonough property front yard. | | | |
| Photo Orientation: Northeast | | | |
| Viewer Position: _____ Inferior _____ x _____ Level _____ Superior | | | |
| View | Notes | | |
| Foreground (0 - 1/2 mile) | Storage pond now dominates foreground view | | |
| Middleground (1/2 - 4 miles) | Nominal change. | | |
| Background (> 4 miles) | Not visible. | | |
| Vividness | | | |
| Feature | Score* | Notes | |
| Landform | 4 | Hills and valley in foreground have been altered to create the storage pond but ridgeline in middleground remains intact. | |
| Vegetation | 4 | Several acres of oak woodland removed to make way for storage pond. | |
| Water Feature | n/a | | |
| Human-Made | 4 | Storage pond has elements that blend into landscape such as water, but also has engineered elements such as a roadway, fence, and liner. | |
| Overall | 4.0 | | |
| Intactness | | | |
| Overall | 3 | Storage pond is a somewhat engineered element in a primarily natural landscape. | |
| Unity | | | |
| Overall | 3.5 | Image is now dominated by the storage pond which appears to have been cut into the hillsides and contains several engineered elements such as a road, chainlink fence, and a liner. | |
| Overall Visual Quality Score | 3.5 | | |

*Score Key:
1 - Very Low; 2 - Low; 3 - Moderately Low; 4 - Average; 5 - Moderately High; 6 - High; 7 - Very High

| Visual Resource Survey: | | ERSP | With Landscaping |
|--|--|---|------------------|
| Key View: Private Property | | | |
| Date: 2/8/08 | | | |
| Viewpoint Description: View toward project from McDonough property front yard. | | | |
| Photo Orientation: Northeast | | | |
| Viewer Position: _____ Inferior _____ x _____ Level _____ Superior | | | |
| View | Notes | | |
| Foreground (0 - 1/2 mile) | Storage pond now dominates foreground view | | |
| Middleground (1/2 - 4 miles) | Nominal change. | | |
| Background (> 4 miles) | Not visible. | | |
| Vividness | | | |
| Feature | Score* | Notes | |
| Landform | 4 | Nominal change. | |
| Vegetation | 4.5 | Some native oak trees replanted. | |
| Water Feature | n/a | | |
| Human-Made | 4.5 | The most highly visible engineered elements such as the fence and roadway closest to the viewpoint have been screened by the landscaping. | |
| Overall | 4.3 | | |
| Intactness | | | |
| Overall | 4 | Storage pond a little less visible with the landscaping. | |
| Unity | | | |
| Overall | 4 | Storage pond a little less visible with the landscaping. | |
| Overall Visual Quality Score | 4.1 | | |

*Score Key:
1 - Very Low; 2 - Low; 3 - Moderately Low; 4 - Average; 5 - Moderately High; 6 - High; 7 - Very High